

Early Journal Content on JSTOR, Free to Anyone in the World

This article is one of nearly 500,000 scholarly works digitized and made freely available to everyone in the world by JSTOR.

Known as the Early Journal Content, this set of works include research articles, news, letters, and other writings published in more than 200 of the oldest leading academic journals. The works date from the mid-seventeenth to the early twentieth centuries.

We encourage people to read and share the Early Journal Content openly and to tell others that this resource exists. People may post this content online or redistribute in any way for non-commercial purposes.

Read more about Early Journal Content at http://about.jstor.org/participate-jstor/individuals/early-journal-content.

JSTOR is a digital library of academic journals, books, and primary source objects. JSTOR helps people discover, use, and build upon a wide range of content through a powerful research and teaching platform, and preserves this content for future generations. JSTOR is part of ITHAKA, a not-for-profit organization that also includes Ithaka S+R and Portico. For more information about JSTOR, please contact support@jstor.org.

Lapis Lazuli. An Hone. Sardachates. A Granat.	3054	Wrought Brass.	8280
An Hone.	3288	Hammer'd Brass.	8349
Sardachates.	3598	A false Guinea.	9075
A Granat.	3978	A true Guinea.	18888
A Golden Marcasit	e. 4589	Sterling Silver.	
A blew Slate with	shining	A brass Half-Crow	
Particles.		Electrum, a Briti	
A mineral stone,	yielding	-	12071
1 part in 160 Me		A Gold Coin of	Barbary.
The Metal thence			17548
ed.	8500	A Gold Medal fr	om Mo-
ed. The (reputed) Sil	ver Ore	rocco.	
of Wales.	7464	AMentz Gold Duca	t.18261
The Metal thence		A Gold, Coin of	
		ders.	
ed. Bilmuth.	9859	A Gold Medal of	Q. Mary.
Spelter.	7065		
Spelter. Spelter Soder.	8362	A Gold Medal of	
Iron of a Key.		eabeth.	19125
Steel.		A Medal esteem'd	l to be
Cast Brass.	8100	near fine Gold.	
			- 3

II. Extracts of some Letters from Mr. John Sturdie of Lancashire concerning Iron Ore; and more particularly of the Hæmatites, wrought into Iron at Milthrop-Forge in that County. Communicated by Dr. Martin Lister, S. R. S.

Townley, March 14. 1674.

SIR

YOU will receive herewith some of the Cinder you desir'd, as also a little of Iron-stone both burnt and unburnt. They have several sorts of Iron-stone, and

of different Natures; for some makes Coldsbire-Iron, that is, such as is brittle, when it is cold; another fort makes Realhire, that is, such as is ant to break if it be hammered, when it is of a dark red Heat, and therefore are never melted down but in mixture, and fo they yield an indifferent good fort of Iron. They have of late made it much better than beretofore, by melting the Sowmetal over again, as likewife by ofing Turf and Charcoal, whereas formerly their Fuel was only Charcoal. They once made Trial of Pit-Coal, but with bad Success. The small dusty part of their Charcoal is useful for burning the Iron-stone; for every 17 Baskets of this burnt Stone they put in one of Brimstone unburnt to make it melt freely, and cast the Cinder. There is no other Cinder swimming above but such like as this I fend you, only sometimes it is more vitrified than it is at other times. They always take it off from the melted Iron with a Coal-rake at a hole in the Furnacemouth before they let the Metal run. There is nothing remains in the bottom of the Hearth, all becomes either Iron or Cinder.

The Furnace is built on the fide of an Hill, the bottom is about two yards square, and so rises perpendicular for a yard or more, which is also lined within with a Wall of the best Fire-stone to keep off the force of the Fire from the Walls of the Furnace: The Bellows (which are very large, and played with Water) enter about the middle of the Focus. The rest of the Furnace is raised upon this 6 or 7 yards square wise, but tapering; so that the sides draw towards each other by degrees, and the top-hole (where they throw in Baskets of Stone and Fewel) is but about \frac{1}{2} a yard square. Into this place they put down a Pole, to know how far it hath rested after a certain time; and when they find it to have subsided about a yard and \frac{1}{2}, then they put in more, till the Furnace be full again.

Thurnbam.

Thurnham, Aug. 12. 1675.

Hough I am in daily expectation of some of the Milthrop Iron-stone, and may possibly get it before this Letter reach you, yet I thought it not convenient any longer to defer the Account I received thereof from a Gentleman concerned in the Work, for sear some of the Circumstances should slip out of my Memory.

of the Circumstances should slip out of my Memory.

The Oar is got in Fournesse (a division of Lancashire) at least 15 Miles from Milthrop. Some of it is hard, but feels soft and smooth on the out-side like Velver. Some is soft as Clay, but all is red, and lies in Beds like Coal.

The Furnace in which it is melted is not above a yard and over, and about the same height. The Hearth is all of Sow-Iron, much of the Shape of a broad-brim'd Hat with the Crown downwards. The Sides are of Stone, arched towards the top; in the midst is a Tunnel at which they put in Charcoal, on which when it is kindled, they put Oar (first broken into pieces as big as a Pigeons Egg) so much as they intend to melt down.

Then they set their Bellows on work, which are moved with Water, and go into the midst of the Furnace-Wall, and keep blowing for some 12 hours, feeding it still with new Charcoal as it settles.

Then they pull out a Stopple at the bottom of the Wall, and out comes all the Glassie-Cinder being very liquid, leaving the Iron in a Lump (for it does not flow) in that Conical Hole in the midst of the Hearth.

This they take out with great Tongs and put under heavy Hammars (played also with Water) whereby after several Heatings (in the same Furnace where it is melted) it is beaten into Barrs. They get about an

U Hundred

Hundred weight of Metal at one melting, which is the Product of about three times so much Oar.

Thurnham, Sept. 25. 1675.

SIR

Send now at last the promised Parcels of Iron Oar, one fort of it seems to be good *Hæmatites*. It seems I either did not rightly apprehend, or was not clearly enough informed by the Person from whom I had the Account I sent you, of the Furnace in which they melt down their Oar.

It is very much like a common Black-smiths, viz. A plain open Hearth or bottom without any enclosing Walls, only where the nose of the Bellows come in through a Wall there is a hollow place (which they call the Furnace) made of Iron Plates, as is also that part of the Hearth next adjoining. This hollow place they fill and up-heap with Charcoal, and lay the Oar (broken small) all round about the Charcoal upon the flat Hearth, to bake it as it were, or neal and thrust it in by little and little into the Hollow, where it is melted by the Blast. The glassie Scoriæ run very thin, but the Metal is never in a perfect Fusion, but settles as it were in a Clod, that they take it out with Tongs, and turn it under great Hammers, which at the same time beat off (especially at first taking out of the Furnace) a deal of courser Scoriæ, and form it after several Heats into Bars. They use no Lime stone or other thing to promote the Flux, for that I enquired particularly. As to other matters my former Relation is exact enough.

POSTSCRIPT.

SIR,

Fter the Sealing of my Letter that comes with this, I met with one who hath promised to send

me some soft Oar, as also a little of a Chrystalline Spar that grows to it, and the rest that you desire.

As to your Queries.

Steel is not made from that they call Steel Oar, but

Iron, such as is made from the rest.

All the Oars that were sent you lie in one Bed or Seam, but the hard Oars lie usually next the Rocks on each side, and the soft Oar in the midst.

The Rocks between which they lie are a grey Lime-

Stone.

There is no rock underneath (as you seem to conceive) for the Oar lies between Rocks on each side, or rather in the Clefts of Rocks which they follow, still digging deeper many Fathoms. Sometimes the said Clefts (which are filled with Oar) are an Inch, sometimes a Foot broad, sometimes three or four Tards, but still one continued Vein running downwards towards the Center of the Earth.

Thurnham, Nov. 14. 1675.

I shall shortly meet with one from Fourness, and shall get you a Resolution of your Queries, as also some of the Oar you defire. They use it frequently, and with great Success, as a Medicine for the Murrain in Cattle. and for all Diseases in Swine, to which last they will

give a good handful or two in Milk.

N. B. This is meant of the soft Oar like Clay. I have this to add, that this Clay Hæmatites is as good, if not better, than that which is brought from the East Indies. Witness the Tea-Pots now to be sold at the Potters in the Poultrey in Cheap side, which not only for Art, but for beautiful Colour too, are far beyond any we have from China. These are made of the English Hæmatites in Staffordshire, as I take it, by two Dutch-men, incomparable Artists.

Westm. May 1.93.

I am, &c. M.L.